

Table 5-5a, LUST Sites in Close Proximity to 4th Street

Map ID No.	Name	Comments
1	Midtown Shopping Center	Groundwater monitoring showed no contamination above Maximum Contaminant Levels. Groundwater flow is to the southeast.
5	Carmen Arrigo	Soil sampling showed no contamination remaining after removal of UST
7A	Sears	Soil samples from excavation below OIS guideline levels
7A	Pueblo Chieftan	Soil samples from excavation below OIS guideline levels
8A	General Refractories	Soil samples from excavation below OIS guideline levels
8B	Cliff Brice Station	Soil contamination removed, groundwater monitoring showed no contamination. Groundwater flow is to the southeast.
9	Loaf N' Jug	Soil samples from excavation below OIS guideline levels
9	Lincoln Service Center	Soil samples from excavation below OIS guideline levels
10A	Star Oil	Hydraulic oil spill of <25 gallons, cleaned up
10C	Johnson's Boiler Shop	No records available on this site
14	Diamond Shamrock	File shows existing UST's but no history of leaks
15	Estes Industries	Groundwater monitoring showed decreasing contamination within property boundary. Groundwater flow is to the east.