


Sight Distance Improvements

Proposed Action - West Detail



Option 1: Maintain existing condition.



Option 2: Construct retaining wall to improve sight distance.